



PASSEN INSPECTIONS AND THERMAL IMAGING

17750 E Lake Jem Rd, Mount Dora FL 32757
 352.530.7343 office 352.530.7361 cell
Infrared Thermal Imaging Report



Today's inspection date: December 20, 2014		Inspection time: 4:00pm
---	--	--------------------------------

Requested for: Henry Aaron	Thermographer: Bo Passen
Street: 755 Homerun Pl	Level: CRT
City/Zip: Tangerine FL, 32777	Status: Certified #2014061902
Current exterior conditions: Cool, overcast, recent rain.	Equipment used: FLIR E8
Approx. interior ambient temp: 62	
Approx. interior relative humidity: 49	
Emissivity value used: .9	


Qualifications: Values conveyed are close estimates and may not reflect exact temperatures, emissivity or distances. Different conditions/influences can have profound effects on targets. Finding exact values would be impractical in a qualitative home inspection. **Images are taken in current loading conditions.** Camera is not typically used on the exterior because of material inconsistencies, rapidly changing environmental conditions and/or the timeframe of the inspection.

- Thermal image 1 No current overheating conditions in sub panel.
- Thermal image 2 Heat leakage at duct work.
- Thermal image 3 Moisture at chimney in attic, verified wet with moisture meter.
- Thermal image 4 Moisture, upstairs ceiling at chimney, verified wet with moisture meter.
- Thermal image 5
- Thermal image 6
- Thermal image 7







1.



2.



3.



4.